



Report for:

Ryan Metzen, Gerald Moralez Entek Consulting Group 3435 American River Drive Suite C Sacramento, CA 95864

Eurofins Built Environment Testing West, LLC

Regarding: Project: 25-7866, UCDMC FP&D; UCDMC, SESP, 1st Floor 2315 Stockton BLVD Sacramento, CA

EML ID: 4232945

Approved by:

Dates of Analysis:

Asbestos PLM: 09-17-2025 and 09-18-2025

Approved Signatory James Schatz

Service SOPs: Asbestos PLM (EPA 40CFR App E to Sub E of Part 763 & EPA METHOD 600/R-93-116, SOP EB-AS-S-1267) NVLAP Lab Code 600255-0

All samples were received in acceptable condition unless noted in the Report Comments portion in the body of the report. The results relate only to the samples as received and tested. The results include an inherent uncertainty of measurement associated with estimating percentages by polarized light microscopy. Measurement uncertainty data for sample results with >1% asbestos concentration can be provided when requested.

Eurofins Built Environment Testing West, LLC ("the Company"), a member of the Eurofins Built Environment Testing group of companies, shall have no liability to the client or the client's customer with respect to decisions or recommendations made, actions taken or courses of conduct implemented by either the client or the client's customer as a result of or based upon the Test Results. In no event shall the Company be liable to the client with respect to the Test Results except for the Company's own willful misconduct or gross negligence nor shall the Company be liable for incidental or consequential damages or lost profits or revenues to the fullest extent such liability may be disclaimed by law, even if the Company has been advised of the possibility of such damages, lost profits or lost revenues. In no event shall the Company's liability with respect to the Test Results exceed the amount paid to the Company by the client therefor.

180 Blue Ravine Rd, Folsom, CA 95630 (833) 465-5857 www.eurofinsus.com/Built

Client: Entek Consulting Group C/O: Ryan Metzen, Gerald Moralez

Re: 25-7866, UCDMC FP&D; UCDMC, SESP, 1st Floor 2315 Stockton BLVD Sacramento, CA

Date of Sampling: 09-17-2025 Date of Receipt: 09-17-2025 Date of Report: 09-18-2025

#### ASBESTOS PLM REPORT

Total Samples Submitted: 15
Total Samples Analyzed: 15
Total Samples with Layer Asbestos Content > 1%: 0

# Location: ECG-25-7866-01A, Light grey, Rolled vinyl sheet flooring w/ mastic, Northeast side of CT Control 1P744.

Lab ID-Version‡: 21168669-1

Sample Layers	Asbestos Content
Gray Flooring	ND
Transparent Mastic	ND
Sample Composite Homogeneity:	Moderate

# Location: ECG-25-7866-01B, Light grey, rolled vinyl sheet flooring w/ mastic, Westside of Corridor 1P740.

Lab ID-Version‡: 21168670-1

Sample Layers	Asbestos Content
Gray Flooring	ND
Transparent Mastic	ND
Gray Leveling Compound	ND
Composite Non-Asbestos Content:	2% Cellulose
Sample Composite Homogeneity:	Moderate

## Location: ECG-25-7866-02A, Tan rolled vinyl sheet flooring w/ mastic southside of CT room 1P742

Lab ID-Version‡: 21168671-1

Sample Layers	Asbestos Content
Beige Flooring	ND
White Mastic	ND
Gray Leveling Compound	ND
Composite Non-Asbestos Content: 2% Cellulose	
Sample Composite Homogeneity:	Moderate

The test report shall not be reproduced except in full, without written approval of the laboratory. The report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the federal government. The Company reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified.

All components not quantified as asbestos content and non-asbestos content are considered to be non-fibrous matrix components. Matrix components may include, but are not limited to, gypsum, paint, silicate minerals, vinyl, binder, calcium carbonate, tar, and foam.

Inhomogeneous samples are separated into homogeneous subsamples and analyzed individually. ND means no fibers were detected. When detected, the minimum detection and reporting limit is less than 1% unless point counting is performed. Floor tile samples may contain large amounts of interference material and it is recommended that the sample be analyzed by gravimetric point count analysis to lower the detection limit and to aid in asbestos identification.

180 Blue Ravine Rd, Folsom, CA 95630 (833) 465-5857 www.eurofinsus.com/Built

Client: Entek Consulting Group C/O: Ryan Metzen, Gerald Moralez

Re: 25-7866, UCDMC FP&D; UCDMC, SESP, 1st Floor 2315 Stockton BLVD Sacramento, CA

Date of Sampling: 09-17-2025 Date of Receipt: 09-17-2025 Date of Report: 09-18-2025

#### ASBESTOS PLM REPORT

Location: ECG-25-7866-02B, Tan rolled vinyl sheet flooring w/ mastic, northside of CT

room 1P742.

Sample Layers	Asbestos Content
Beige Flooring	ND
White Mastic	ND
Gray Leveling Compound	ND
Composite Non-Asbestos Content:	2% Cellulose
Sample Composite Homogeneity:	Moderate

#### Location: ECG-25-7866-03A, White, orange peel wall texture, south wall, corridor 1P740

Lab ID-Version 1: 21168673-1

Sample Layers	Asbestos Content
White Texture	ND
Sample Composite Homogeneity:	Good

#### Location: ECG-25-7866-03B, White, orange peel wall texture, north wall, corridor 1P740

Lab ID-Version 1: 21168674-1

Sample Layers	Asbestos Content
White Texture	ND
Sample Composite Homogeneity:	Good

#### Location: ECG-25-7866-03C, White, orange peel wall texture, entry to CT room 1P740 Lab ID-Version: 21168675-1

Sample Layers	Asbestos Content
White Texture	ND
Sample Composite Homogeneity:	Good

The test report shall not be reproduced except in full, without written approval of the laboratory. The report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the federal government. The Company reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified.

All components not quantified as asbestos content and non-asbestos content are considered to be non-fibrous matrix components. Matrix components may include, but are not limited to, gypsum, paint, silicate minerals, vinyl, binder, calcium carbonate, tar, and foam.

Inhomogeneous samples are separated into homogeneous subsamples and analyzed individually. ND means no fibers were detected. When detected, the minimum detection and reporting limit is less than 1% unless point counting is performed. Floor tile samples may contain large amounts of interference material and it is recommended that the sample be analyzed by gravimetric point count analysis to lower the detection limit and to aid in asbestos identification.

180 Blue Ravine Rd, Folsom, CA 95630 (833) 465-5857 www.eurofinsus.com/Built

Client: Entek Consulting Group C/O: Ryan Metzen, Gerald Moralez

Re: 25-7866, UCDMC FP&D; UCDMC, SESP, 1st

Floor 2315 Stockton BLVD Sacramento, CA

Date of Sampling: 09-17-2025 Date of Receipt: 09-17-2025 Date of Report: 09-18-2025

#### ASBESTOS PLM REPORT

Location: ECG-25-7866-04A, White, drywall / joint compound, westside corridor 1P740

Lab ID-Version‡: 21168676-1

Sample Layers	Asbestos Content	
White Joint Compound	ND	
Cream Tape	ND	
Brown/White Drywall with Brown Paper	ND	
Composite Non-Asbestos Content:	15% Cellulose < 1% Glass Fibers	
Sample Composite Homogeneity:	Poor	

# $Location: ECG-25-7866-04B, White, drywall\ /\ joint\ compound, northwest\ corner,\ CT\ control\ 1P744$

Lab ID-Version‡: 21168677-1

Sample Layers	Asbestos Content	
White Joint Compound	ND	
Cream Tape	ND	
Brown/White Drywall with Brown Paper	ND	
Composite Non-Asbestos Content:	15% Cellulose	
	< 1% Glass Fibers	
Sample Composite Homogeneity:	Poor	

#### Location: ECG-25-7866-05A, Grey, Concrete flooring, northwest side CT 1P746

Lab ID-Version‡: 21168678-1

Lab ID-Version 1: 21168679-1

Sample Layers	Asbestos Content
Gray Concrete	ND
Sample Composite Homogeneity:	Good

#### Location: ECG-25-7866-05B, Grey, Concrete flooring, southwest side 1P746

**Sample Composite Homogeneity:** Good

Sample Layers
Gray Concrete

	•
Asbestos Content	
ND	

The test report shall not be reproduced except in full, without written approval of the laboratory. The report must not be used by the client to
claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the federal government. The Company reserves the
right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified.

All components not quantified as asbestos content and non-asbestos content are considered to be non-fibrous matrix components. Matrix components may include, but are not limited to, gypsum, paint, silicate minerals, vinyl, binder, calcium carbonate, tar, and foam.

Inhomogeneous samples are separated into homogeneous subsamples and analyzed individually. ND means no fibers were detected. When detected, the minimum detection and reporting limit is less than 1% unless point counting is performed. Floor tile samples may contain large amounts of interference material and it is recommended that the sample be analyzed by gravimetric point count analysis to lower the detection limit and to aid in asbestos identification.

180 Blue Ravine Rd, Folsom, CA 95630 (833) 465-5857 www.eurofinsus.com/Built

Client: Entek Consulting Group C/O: Ryan Metzen, Gerald Moralez

Re: 25-7866, UCDMC FP&D; UCDMC, SESP, 1st Floor 2315 Stockton BLVD Sacramento, CA

Date of Sampling: 09-17-2025 Date of Receipt: 09-17-2025 Date of Report: 09-18-2025

#### ASBESTOS PLM REPORT

Location: ECG-25-7866-06A, Tan, Vinyl base cove w/ mastic, south wall sorridor 1P742

Lab ID-Version‡: 21168680-1

Sample Layers	Asbestos Content
Beige Cove Base	ND
Sample Composite Homogeneity: Good	

**Comments:** No mastic present for analysis

Location: ECG-25-7866-06B, Tan, Vinyl base cove w/ mastic, entry CT room 1P742

Lab ID-Version‡: 21168681-1

Sample Layers	Asbestos Content	
Beige Cove Base	ND	
Beige Mastic	ND	
White Joint Compound	ND	
Sample Composite Homogeneity: Moderate		

# Location: ECG-25-7866-07A, White, rolled vinyl sheet flooring w/ mastic, southside CT room 1P742

Lab ID-Version‡: 21168682-1

Sample Layers	Asbestos Content	
Gray Flooring	ND	
White Mastic	ND	
Gray Leveling Compound	ND	
Composite Non-Asbestos Content:	2% Cellulose	
Sample Composite Homogeneity:	Poor	

# Location: ECG-25-7866-07B, White, rolled Vinyl sheet flooring w/ mastic, northside CT room 1P742

Lab ID-Version‡: 21168683-1

Sample Layers	Asbestos Content
Gray Flooring	ND
White Mastic	ND
Gray Leveling Compound	ND
Composite Non-Asbestos Content:	2% Cellulose
Sample Composite Homogeneity:	Poor

The test report shall not be reproduced except in full, without written approval of the laboratory. The report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the federal government. The Company reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified.

All components not quantified as asbestos content and non-asbestos content are considered to be non-fibrous matrix components. Matrix components may include, but are not limited to, gypsum, paint, silicate minerals, vinyl, binder, calcium carbonate, tar, and foam.

Inhomogeneous samples are separated into homogeneous subsamples and analyzed individually. ND means no fibers were detected. When detected, the minimum detection and reporting limit is less than 1% unless point counting is performed. Floor tile samples may contain large amounts of interference material and it is recommended that the sample be analyzed by gravimetric point count analysis to lower the detection limit and to aid in asbestos identification.

180 Blue Ravine Rd, Folsom, CA 95630 (833) 465-5857 www.eurofinsus.com/Built

Client: Entek Consulting Group C/O: Ryan Metzen, Gerald Moralez

Re: 25-7866, UCDMC FP&D; UCDMC, SESP, 1st Floor 2315 Stockton BLVD Sacramento, CA

Date of Sampling: 09-17-2025 Date of Receipt: 09-17-2025 Date of Report: 09-18-2025

#### ASBESTOS PLM REPORT

#### PROJECT ANALYST AND SIGNATORY REPORT

### **Project Analyst**

Analyst: Brittany Quiring

The test report shall not be reproduced except in full, without written approval of the laboratory. The report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the federal government. The Company reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified.





ENTEK CONSULTING GROUP, INC. 3435 AMERICAN RIVER DRIVE, SUITE C SACRAMENTO, CA 95864 (916) 632-6800 PHONE mainoffice@entekgroup.com

Date of Sampling: 9-17-25 Job Number: 25-7866 Client Name: UCDMC FP&D

Site Address: UCDMC, SESP, 1st Floor

2315 Stockton BLVD Sacramento, CA 95817 Lab: Eurofins/EmLab P&K - Folsom Collected by: Gerald Moralez

Turnaround Time: 1-day, Thursday, 9-18-25 Analysis Requested: Asbestos by PLM with

Dispersion Staining

Special Instructions: Stop analysis upon first positive result (>1%) for sample in a series. Also stop

analysis upon first positive result (>1%) in the joint compound for sample series.

Please e-mail results at gmoralez@entekgroup.com, mainoffice@entekgroup.com and rmetzen@entekgroup.com as soon as available and include copy of submittal with those results.

SAMPLE#	MATERIAL DESCRIPTION/LOCATION			
ECG-25-7866-01A	A Light Grey, Rolled Vinyl Sheet Flooring w/ Mastic, Northeast side of CT Control 1P74			
ECG-25-7866-01B	Light Grey, Rolled Vinyl Sheet Flooring w/ Mastic, Westside of Corridor 1P740.			
ECG-25-7866-02A	Tan Rolled Vinyl Sheet Flooring w/ Mastic, Southside of CT Room 1P742.			
ECG-25-7866-02B	Tan Rolled Vinyl Sheet Flooring w/ Mastic, Northside of CT Room 1P742.			
ECG-25-7866-03A	White, Orange Peel Wall Texture, South Wall, Corridor 1P740.			
ECG-25-7866-03B	White, Orange Peel Wall Texture, North Wall, Corridor 1P740.			
ECG-25-7866-03C	White, Orange Peel Wall Texture, Entry to CT Room 1P742.			
ECG-25-7866-04A	White, Drywall / Joint Compound, Westside Corridor 1P740.			
ECG-25-7866-04B	White, Drywall / Joint Compound, Northwest Corner, CT Control 1P744.			
ECG-25-7866-05A	Grey, Concrete Flooring, Northwest Side CT 1P746.			
ECG-25-7866-05B	Grey, Concrete Flooring, Southwest Side 1P746.			
ECG-25-7866-06A	Tan, Vinyl Base Cove w/ Mastic, South Wall, Corridor 1P740.			
ECG-25-7866-06B	Tan, Vinyl Base Cove w/ Mastic, Entry CT Room 1P742.			
ECG-25-7866-07A	White, Rolled Vinyl Sheet Flooring w/ Mastic, Southside CT Room 1P742.			
ECG-25-7866-07B	White, Rolled Vinyl Sheet Flooring w/ Mastic, Northside CT Room 1P742			

Https://entekgroupinc.sharepoint.com/sites/Entekgroup/Shared Documents/Clients/UCDMC - FP&D 23-6675+/25-7866 SESP CT Ste 1P740/Bulk Asb/BLK ASB COC 9-17-25.docx

Delivered by:

Received by:

Date

Date:

9/17/25 Time:

7 17 25 Time: 3:29 AM/FM)

3:29 AM/P)/Q

. \_

Page 7 of 7



### MicroTest Laboratories, Inc. | AIHA ELPAT #160934

3110 Gold Canal Dr, Ste. A, Rancho Cordova, CA 95670 PH 916.567.9808 | FX 916.404.0302

www.microtestlabsinc.com | service@microtestlabsinc.com

\*\*\*for office use only\*\*\*

**Project ID** 

71323

**CLIENT INFORMATION** 

Entek Consulting Group, Inc

Name

Company

**Address** 3435 American River Drive

Sacrmento, CA 95864

**Phone** 916.632.6800

Email mainoffice@entekgroup.com

SAMPLE

Wednesday, September 17, 2025

Date Time JOB SITE INFORMATION Sampler Gerald Moralez

Project UCDMC FP&D

SiteUCDMC, SESP, 1st FloorAddress2315 Stockton Boulevard

Sacramento, CA 95817

**Job** # 25-7866

PO #

**Micro**Test Laboratories

Analytical Report

### Lead in Paint/Bulk Analysis by Flame AA - EPA METHOD 7420/7000B

Client	Laboratory	Client			Reporting	
Sample ID	Sample ID	Sample Description	Matrix	Results	Limits (RL)	Comments
ECG-25-	71323-1	White Paint / On Drywall Systems, South Wall, CT	Paint/Bulk	<rl %="" td="" wt<=""><td>0.01 %Wt</td><td></td></rl>	0.01 %Wt	
7866-01Pb		1P742		<rl ppm<="" td=""><td>100 PPM</td><td></td></rl>	100 PPM	

Date Received:Wednesday, September 17, 2025Date Analyzed:Thursday, September 18, 2025Date Reported:Thursday, September 18, 2025

Analyst: Lexie Cepeda

Authorized Signatory:

Kelly Favero - Lab Manager

This report applies to the standards and procedures indicated to the specific samples analyzed. Samples have NOT been corrected for blank values. EPA 3050B Mod.



Project ID: 71323

Client: Entek

Received Date: 09/17/25

Count: 1 TAT: SD

ENTEK CONSULTING GROUP, INC.

3435 AMERICAN RIVER DRIVE SACRAMENTO, CA 95864 (916) 632-6800 PHONE mainoffice@entekgroup.com

Date of Sampling: 9-17-25 Job Number: 25-7866

Client Name: UCDMC FP&D

Site Address: UCDMC, SESP, 1st Floor

2315 Stockton BLVD Sacramento, CA 95817 Lab: MicroTest Laboratories Collected by: Gerald Moralez

Turnaround Time: Nextday, Thursday, 9-18-25 Analysis Requested: Flame by Atomic Absorption

### Special Instructions:

Please e-mail results at gmoralez@entekgroup.com & mainoffice@entekgroup.com as soon as available and include copy of submittal with those results.

SAMPLE#	MATERIAL DESCRIPTION/LOCATION		
ECG-25-7866-01Pb	White Paint / On Drywall Wall Systems, South Wall, CT 1P742.		

Https://entekgroupinc.sharepoint.com/sites/Entekgroup/Shared Documents/Clients/UCDMC - FP&D 23-6675+/25-7866 SESP CT Ste 1P740/Bulk Pb/BLK Pb COC 9-17-25.docx

Delivered by:

mfor en Emma Cooper

Date:

17,25 Time: 3:45 AM/PM

Received by:

Date:

9 / 17 / 25 Time: 3:45 AM/PMD